



**US Army Corps
of Engineers®**

Detroit District
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6797
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L05-09

Date: 13 APRIL 2005

Waterway: LAKE MICHIGAN

Location: MICHIGAN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL NEW BUFFALO HARBOR

1. Condition surveys performed within the Federal navigation channel at New Buffalo Harbor, Michigan during March 2005, indicate shoaling as shown on the back of this sheet.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L05-09. Internet address: <http://www.lre.usace.army.mil> Go to: Detroit Home Page, Who We Are, Operations Office Home Page.

DONALD P. LAUZON
Lieutenant Colonel, U.S. Army
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2005.



THE INFORMATION DEPICTED ON THIS MAP REPRESENTS THE RESULTS OF SURVEYS MADE ON THE DATES INDICATED AND CAN ONLY BE CONSIDERED AS INDICATING THE GENERAL CONDITIONS EXISTING AT THAT TIME.

SURVEYED: MARCH 2005

ALL SOUNDINGS ARE REFERENCED TO IGLD 1985 FOR LAKE MICHIGAN, ELEVATION 577.5 FT. ABOVE MEAN SEA LEVEL AT RIMOUSKI, QUEBEC. A HYDRAULIC CORRECTOR OF 0.32 FT. WAS APPLIED.



Shoals indicate least available depth below LWD

NEW BUFFALO HARBOR, MI

CONDITION OF CHANNEL

ISSUED: 13 APRIL 2005

U.S. Army Engineer District, Detroit